





ARCHITECTURAL FINISHES



General Information

Panel dimensions: 600mm square x 26mm thick
 Panel weight: 22kg
 High performance 12.5mm thick calcium sulphate core
 Core encased in 0.5mm thick zinc plated sheet steel tray
 13mm thick Quartzstone® surface covering
 Fully accessible and interchangeable panels



Calcium sulphate core in a formed galvanised steel tray with a 13mm Quartzstone®

Performance chart

Finished floor height	Understructure	System weight	Working static loads		Safety factor	Panel deflection
			Point load	Uniformly distributed load		
60 - 110mm	Kped01	64kg/m ²	3kN	15kN/m ²	2	less than 2.5mm
80 - 450mm	Kped04	65kg/m ²	3kN	15kN/m ²	2	less than 2.5mm
450 - 600mm	Kped04 with snap-on stringers	66kg/m ²	3kN	15kN/m ²	2	less than 2.5mm
600 - 1000mm	Kped03 with snap-on stringers	68kg/m ²	3kN	15kN/m ²	2	less than 2.5mm



10 year Limited Warranty

Axia Architectural Limited, makes no warranty, whether express, implied or statutory, other than the that the material sold is free from defects in materials and workmanship with normal use and service, when installed and maintained with their recommendations.

THIS WARRANTY IS THE SOLE AND EXCLUSIVE WARRANTY PROVIDED BY AXIA ARCHITECTURAL LIMITED AND IS IN LIEU OF ANY OTHER WARRANTY OF ANY KIND, EXPRESS OR IMPLIED, INCLUDING BUT NOT LIMITED TO ANY WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. NO WAIVER, ALTERATION, ADDITIONS OR MODIFICATIONS OF THE FOREGOING CONDITIONS SHALL BE VALID UNLESS MADE IN WRITING AND SIGNED BY AN OFFICER OF AXIA ARCHITECTURAL LIMITED.

All statements, technical information and recommendations concerning products sold or samples provided by Axia Architectural Limited are based upon tests believed to be reliable but do not constitute a warranty.

ALL PRODUCTS ARE SOLD, AND SAMPLES OF PRODUCTS PROVIDED, WITH THE UNDERSTANDING THAT BUYER HAS INDEPENDENTLY DETERMINED THE SUITABILITY OF SUCH PRODUCTS FOR ITS PURPOSES.

In case of a problem Buyer must contact the contractor who installed the product upon discovery of a problem with a product. If the contractor is unable to remedy the problem and Buyer believes the problem is covered by the warranty provided herein, or Buyer is dissatisfied with the contractor's response, Buyer must notify Axia Architectural Limited in writing by registered mail at the following address of any failure to conform to this warranty after the installation date and within thirty (30 days) after the claimed defect first arises:

Axia Architectural Limited
6 Wellbrae
Stonehouse
ML9 3ED

Buyer must retain all information and documents related to the problem until the matter is resolved. After Axia Architectural Limited is so notified, they reserve the right to have an authorized representative inspect and verify the defect. On receipt of notification, Axia Architectural Limited shall correct any product that they determine defective in materials or workmanship by, at its option, repairing the defective product or replacing such product from regular inventory product lines.



Correction of nonconformities, in the manner and for a period of time provided above, shall constitute fulfilment of all obligations and liabilities of Axia Architectural Limited to the buyer relating in any way to the problem. The remedies set forth in this instrument are exclusive and represent Buyer's sole remedy. Axia Architectural Limited shall not be liable for special, indirect, consequential or incidental damages of any kind. Any action for breach pursuant to this warranty must be commenced within one year after the cause of action has occurred.

This limited warranty does not cover:

- 1) Any problems with the products classified as irregulars, seconds or remnants sold "as is";
- 2) problems due to improper installation or maintenance, or misapplication of maintenance materials, which are not in accordance with Axia Architectural Limited written instructions;
- 3) Damage in use due to rolling loads, gouges, punctures, stains, scratches, scuffs, cigarettes or other burning agents, discoloration caused by adhesives, maintenance materials or tracking residue from other surfaces, or any improper misuse of or negligence or accident in connection with the product;
- 4) Problems due to moisture, alkali or hydrostatic pressure in the sub floor;
- 5) Materials installed with visible defects or colour variation and not disclosed by Buyer on installation;
- 6) Problems due to sub floor or supporting panels failure or irregularities;
- 7) Premature wear caused by defective, worn or dysfunctional casters or other mechanical applications; or
- 8) Labour or other costs resulting from removal and/or replacement of a product.



ARCHITECTURAL FINISHES



Normal machine finish – Deformation of arch max.0.5 mm

**QUARTZSTONE® FLOOR TILE AND CALCIUM SULPHATE
RAISED ACCESS FLOOR PANEL 599 x 599 x 10 mm**